


PWD LOGO	PUBLIC WORKS DEPARTMENT PWD NO. 1 THANE, 8 TH FLOOR, TMC PARKING PLAZA BUILDING, NEAR JUPITAR HOSPITAL, THANE (W) - 400601	MAHARASHTRA STATE LOGO
Telephone No.: 022 25369293	Website: www.pwd.maharashtra.gov.in	Email: thane1.ee@mahapwd.gov.in
Outward No.: Vi/Sa.Bam.Vi/Thane-1/Rekha Shakha / 7635		Date: 06/08/2026

To,
Shri Vardhman Education Trust,
Tapovan Vidyalaya,
Anjurphata, Tal. Bhiwandi,
Thane.



Subject: Regarding issuance of Building Stability Certificate.

Reference: 1. Letter from Shri Vardhman Education Trust, Tapovan Vidyalaya, Anjurphata, Tal. Bhiwandi, Dist. Thane, Outward No. SVET/003/25-26, dated 02/12/2025.
2. Letter from Sub-Divisional Engineer, P.W. Sub-Division Bhiwandi, Thane, Outward No. AU/Sa.Bam.UVi/Bhi/Prasha/1109, dated 10/07/2026.

As per your request in the referenced letter, the Sub-Divisional Engineer, Public Works Sub-Division Bhiwandi, Thane, conducted a physical inspection on 09/02/2026 of the school building of Shri Vardhman Education Trust, Tapovan Vidyalaya, Anjurphata, Tal. Bhiwandi, Dist. Thane. In accordance with the inspection report, the certificate certifying that the school building is safe/stable is countersigned and enclosed herewith.

Enclosure: Certificate

(Sachin P. Patil)

Executive Engineer

P.W. Division No. 1, Thane

Copy to: Sub-Divisional Engineer, P.W. Sub-Division Bhiwandi, Thane, forwarded for information.

NOTED & REGISTERED

Sr. No. 159 Page No. 99

Book No. 01 Date 13/08/2026

TRUE COPY


PRAVINKUMAR L. JAIN

B.Com., LL.B.,

ADVOCATE & NOTARY GOVT. OF INDIA

93-1, Bramhan Aley, Block No. 13, Third Floor,
Guru Ashish Co-operative Housing Society Limited,
Bhiwandi, Dist. Thane, Maharashtra.





कार्यकारी अभियंता यांचे कार्यालय
सा.बां.विभाग क्र.१ ठाणे, ८ वा मजला, ठामपा
पार्किंग प्लाझा बिल्डिंग, ज्यूपिटर हॉस्पिटल
जवळ, ठाणे (प)-४००६०१



महाराष्ट्र शासन

दुरध्वनी क्र. ०२२ २५३६९२९३

Web Site:-www.pwd.maharashtra.gov.in

Email :thane1.ee@mahapwd.gov.in

जा.क्र.वि/सा.बां.वि/ठाणे-१/रेखा शाखा/ ७६३५

दिनांक:- ६/८/२०२६

प्रति,
श्री.वर्धमान एज्युकेशन ट्रस्ट,
तपोवन विद्यालय,
अंजूरफाटा ता. भिवंडी
ठाणे.

विषय:-

इमारत सुरक्षित असल्याबाबत दाखला देण्याबाबत.

संदर्भ:-

१. श्री. वर्धमान एज्युकेशन ट्रस्ट, तपोवन विद्यालय अंजूरफाटा ता. भिवंडी जि. ठाणे यांचे पत्र जा.क्र. SVET/००३/२५-२६, दि. २/१२/२०२५
२. उपविभागीय अभियंता, सा. बां. उपविभाग भिवंडी, ठाणे यांचे पत्र जा. क्र.अउ/सा.बांउवि/भि/प्रशा/११०९ दिनांक १०/०७/२०२६.

आपले संदर्भित पत्रान्वये मागणी श्री. वर्धमान एज्युकेशन ट्रस्ट, तपोवन विद्यालय अंजूरफाटा ता. भिवंडी जि. ठाणे या शाळेच्या इमारतीची उपविभागीय अभियंता, सा. बां. उपविभागीय भिवंडी ठाणे यांनी दिनांक ०९/०२/२०२६ रोजी प्रत्यक्ष पाहणी केली असून अहवालाच्या अनुषंगाने शालेय इमारत सुरक्षित असल्याबाबतचे प्रमाणपत्र प्रतिस्वाक्षरी करून सोबत पाठविण्यात येत आहे.

सोबत:- प्रमाणपत्र.


(सचिन प्र. पाटील)
कार्यकारी अभियंता
सा. बां. विभाग क्र.१
ठाणे.

प्रत:- उपविभागीय अभियंता, सा. बां. उपविभाग भिवंडी ठाणे यांना माहितीसाठी रवाना.



Building Stability Certificate

Certified that the Educational Building belonging to the Shree Vardhaman Education Trust at Known as Tapovan Vidhyalay CBSE School, Near Jaina Mangal Vatika, New Kamatghar Road, Anjurphata Bhiwandi-421302 Dist. Thane has been inspected by this Office on dated 9.02.2026 At the time of the Inspection of such educational building is seems sound and Stable enough to bear the Maximum load of 45 Nos of students per class room of existing 30 Nos.& other 38 [Lab, Staff rooms , activity room]and it will be stable to bear the existing live load for building is used for school purpose as on date, except in the case of natural calamity.

It is also certify that, the following general terms and conditions may be full fill by the management in the stipulated period.

1. Fire fighting arrangement should be kept ready for 24 hours and should renewed twice in a year.
2. The rooms should be kept well ventilated and should be kept as per norms.
3. The responsibility of structural stability of the building rests, with the owner and their private Architecture and Designers.
4. The owner and management will be held responsible for any accident or mischief occurs.
5. Any activities in the school should not affect traffic attention to cause accident etc. by way of noise and light.
6. Toilet, W.C. etc. shall be kept clean for its purpose of use.
7. The work should be as per sanctioned plan from Competent Authority.
8. Width of stairs shall be 1250 mm as per N.B.C. 4:11:8.
9. N.O.C. of any other Department such as Corporation, Health Department, Fire Brigade etc. should be taken.
10. In case of faulty or leakage A.C. sheet should be replaced immediately.
11. Fire prevention equipment is being renewed from time to time.
12. This office has got full power to check the school rooms at any time. If any fault or alternation of served certificate is noticed this permission shall be treated as cancelled.

This Certificate is valid for one year from the date of issue it will be renew time to time every year before expiry date.

The necessary Inspection fees Rs. 1000/- [One Thousand rupees only] paid by the management vide D.R. No.01812 dt. 5.2.2026 and it s credited on account of 0059 P.W. remittance into treasury S.B.I. at Bhiwandi

Counter Signed


Deputy Engineer,
Bhiwandi [P.W.]Sub-Division,
Bhiwandi


Executive Engineer,
Thane [P.W.] Division No.1
Thane